ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M02115
Date Received: 03/20/08
Date Extracted: 03/25/08
Date Analyzed: 03/25/08
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO M-02115, F&BI 803212
Lab ID: 803212-01 x10
Data File: 803212-01 x10.043
Instrument: ICPMS1
Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 77 60 125

Concentration
Analyte: ug/L (ppb)

Chromium 491
Nickel 353
Copper 288
Zinc 13.1

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 03/25/08
Date Analyzed: 03/25/08
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO M-02115, F&BI 803212
Lab ID: I8-097 mb
Data File: I8-097 mb.036
Instrument: ICPMS1

Operator: hr

Internal Standard: % Recovery: Germanium 75 Lower Limit: 60 Upper Limit: 125

Concentration
Analyte: ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 03/28/08 Date Received: 03/20/08

Project: Metro Self Monitor, PO M-02115, F&BI 803212

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 803234-15 (Duplicate)

				Relative	
		Sample	Duplicate	Percent	Acceptance
Analyte	Reporting Units	Result	Result	Difference	Criteria
Chromium	ug/L (ppb)	2.01	1.88	7	0-20
Nickel	ug/L (ppb)	3.25	3.17	2	0-20
Copper	ug/L (ppb)	3.39	3.04	11	0-20
Zinc	ug/L (ppb)	14.8	13.5	9	0-20

Laboratory Code: 803234-15 (Matrix Spike)

		Spike	Sample	Percen Recover	Acceptance	
Analyte	Reporting Units	Level	Result	MS	Criteria	-1,11
Chromium	ug/L (ppb)	20	2.01	103	50-150	
Nickel	ug/L (ppb)	20	3.25	95	50-150	i had
Copper	ug/L (ppb)	20	3.39	92	50-150	
Zinc	ug/L (ppb)	50	14.8	96 b	50-150	

Laboratory Code: Laboratory Control Sample

		Spike	Percen Recover	. Na d. A.	:e
Analyte	Reporting Units	Level	LCS	Criteria	
Chromium	ug/L (ppb)	20	110	70-130	
Nickel	ug/L (ppb)	20	103	70-130	74.5
Copper	ug/L (ppb)	20	102	70-130	
Zinc	ug/L (ppb)	50	93	70-130	

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr-The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

March 28, 2008



INVOICE #08ACU0328-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M-02115, F&BI 803212 - Results of testing requested by Gerry Thompson for material submitted on March 20, 2008.

1 sample analyzed for Total Chromium, Copper, Nickel and Zinc by Method 200.8 @ \$80 per sample \$80.00

Rush Charges (4 day) 60% of \$80.00

Amount Due \$128.00

FEDERAL TAX ID *(b) (6)

803212		* * * * * * * * * * * * * * * * * * * *	SAI	MPLE CHAI	n of Ci	JST	OD	Y	M	Ė	0	3/2	lo,	108	5			AZ	74	
Send Report To Geroad Thompson				SAMPLERS/(signature)								Page # of TURNAROUND TIME								
Company ALASKAN Copper Works				PROJECT NAME/NO. PO					#	☐ Standard (2, Weeks)										
Address 628 S Handone ST				metro Self monitor m-					·02	RUSH Charges authorized by:						y:				
				REMARKS							-	SAMPLE DISPOSAL								
City, State, ZIP SeAT	7 201	200 60	7/									☐ Dispose after 30 days ☐ Return samples								
Phone # 206-571-603	Fax # <u>200</u>	-581-4	507									□ Will call with instructions								
			,						- /	ANA	LYSI	SR	EQU	QUESTED						
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	OR OW WELL						Notes		
MOZIIS	01	3/20	1:00 pm	H20								Ť	-					è		
		# 12 F													145					
																		,		
2.									1											
					•				7											
					£ .				1											
	1								\dashv					-						
		5.			·							\neg				T		• ••••••••		
Friedman & Bruya, Inc.		SIGNATUI	RE		PRINT	NA	ME			工		CC	MP	ANY		士	DATE	TII	ME	
3012 16th Avenue West	Relinquished by			- Geneld Thorpson						Acco 3/20/08					2003	en				
Seattle, WA 98119-	Received by: Jun Jum			Whan Phan						Feb 3/20/08 2:00						5				
Ph. (206) 285-8282	Relinquished b	y:/		. [
Fax (206) 283-5044 Received by:			- 4 ~	•					T		٠,	Sar	nole	S T		湖海	16	70		

FORMS\COC\COC.DOC

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

March 28, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on March 20, 2008 from the Metro Self Monitor, PO M-02115, F&BI 803212 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0328R.DOC